RISK ASSESSMENT WIZARD



MASONRY AND BRICKLAYING

Safety Guide

Construction Trade

0	16	3
Key Benefits	Control Measures	Checklist Items

KEY HAZARDS & CONTROL MEASURES

Silica Dust

- ✔ Use water suppression when cutting
- ✔ On-tool extraction for power tools
- ✔ RPE with P3 filters where needed
- ✔ Health surveillance for exposed workers

Cement Burns

- ✔ Wear waterproof gloves
- ✔ Use barrier cream
- ✔ Wash skin promptly
- ✔ Wear long sleeves and trousers

Manual Handling

- ✔ Use mechanical handling where possible
- ✔ Keep materials at working height
- ✔ Rotate tasks to reduce repetition
- ✔ Training in lifting techniques

Working at Height

- ✔ Properly erected scaffold with guard rails
- ✔ Regular scaffold inspections
- ✔ Safe access maintained
- ✔ Toe boards to prevent falling materials

RISK ASSESSMENT WIZARD

Take Your Safety To The Next Level

Create professional, customized risk assessments for your organization with our easy-to-use online wizard.

390+

Activity Templates

Pre-loaded hazards & controls for every activity

100%

Customizable

Add your branding & tailor to your needs

- ✔ Instant PDF & print-ready documents
- ✔ Store and update assessments online
- ✔ Add your logo & organization details
- ✔ Reuse and duplicate assessments
- ✔ Works on any device

Start Free at riskassessmentwizard.com

No credit card required - Try it free today