



RISK ASSESSMENT
— WIZARD —



MASONRY AND BRICKLAYING

Safety Guide

Construction Trade

0

Key Benefits

16

Control Measures

3

Checklist Items

KEY HAZARDS & CONTROL MEASURES**Silica Dust**

- ✓ Use water suppression when cutting
- ✓ RPE with P3 filters where needed
- ✓ On-tool extraction for power tools
- ✓ Health surveillance for exposed workers

Cement Burns

- ✓ Wear waterproof gloves
- ✓ Wash skin promptly
- ✓ Use barrier cream
- ✓ Wear long sleeves and trousers

Manual Handling

- ✓ Use mechanical handling where possible
- ✓ Rotate tasks to reduce repetition
- ✓ Keep materials at working height
- ✓ Training in lifting techniques

Working at Height

- ✓ Properly erected scaffold with guard rails
- ✓ Safe access maintained
- ✓ Regular scaffold inspections
- ✓ Toe boards to prevent falling materials



RISK ASSESSMENT
— WIZARD —

Take Your Safety To The Next Level

Create professional, customized risk assessments for your organization with our easy-to-use online wizard.

390+

Activity Templates

Pre-loaded hazards & controls for every activity

100%

Customizable

Add your branding & tailor to your needs

- ✓ Instant PDF & print-ready documents
- ✓ Store and update assessments online
- ✓ Add your logo & organization details
- ✓ Reuse and duplicate assessments
- ✓ Works on any device

Start Free at riskassessmentwizard.com

No credit card required - Try it free today